

CEE-BEE STRIPPER A-29SCW

by Cee-Bee®



d a t a s h e e t

CEE-BEE STRIPPER A-29SCW is a thickened paint stripper. Rapidly and effectively strips a wide variety of coatings

BENEFITS

- Strips alkyd and modified alkyd enamels, nitrocellulose and acrylic, lacquers, most moisture cured polyurethanes and many air dried epoxies.
- Readily removes carbon deposits from bare metal surfaces.
- Viscous. Clings to incline, vertical and overhead surfaces.
- Safe on all common aircraft structural metals, including aluminum, cadmium plated steel, mild steel, magnesium and high strength steel.
- Non-flammable. Low toxicity.
- Contains no phenolics or cyanides. Surfactants biodegradable.

CONFORMS TO

- **BOEING D6-17487**
- **DOUGLAS CSD-1, TYPE III**
- **UNITED AIRLINES SERVICE MANUAL CSM 5.01**

**NOTE: To place an order, call or Fax Customer Service at
800-327-0466 / FAX 1-216-441-1377
Cee-Bee Stripper A-29SCW Product Code # 23012**



NOTES PRIOR TO HANDLING

Before using your McGean-Rohco, Inc. products, all safety and operating instructions should be read and understood. If you have any questions, please contact your McGean-Rohco representative before proceeding.

USE PROCEDURES

Paint Stripping

1. Surface should be dry and below 110°F (43°C).
2. Apply a very thin, uniform film of stripper with brush, roller or non-atomizing spray. When the coating begins to absorb the stripper, apply another uniform film.
3. Allow the stripper to dwell until the coating is loosened from the substrate.
4. Agitate with a stiff bristle brush and reapply stripper to areas not completely released.
5. When stripping action is complete, squeegee or scrap off loosened coating and excess stripper and collect for disposal.
6. Rinse with high pressure water to remove paint and stripper residues.

Carbon Removal from Unpainted Metals

1. Surface should be dry and below 110°F (43°C).
2. Apply a uniform film of stripper with brush, roller or non-atomizing spray. Allow stripper to dwell until carbon begins to soften.
3. Agitate with a stiff bristle brush.
4. Rinse with flowing water. Do not allow stripper or rinse water to contact any adjacent painted area.